

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 47 LONG 5.07125646414344300 LAT 52.32990822444608000	
2022 Update Muiden	S1-S1.HN - M - 48 LONG 5.07069928895486800 LAT 52.32928374344360000	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 49 LONG 5.07164721727117900 LAT 52.33090637877778000	
2022 Update Muiden	S1-S1.HN - M - 50 LONG 5.07151928292060200 LAT 52.33077648113212000	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 51 LONG 5.07063079173306900 LAT 52.33154973071155000	
2022 Update Muiden	S1-S1.HN - M - 52 LONG 5.07053880025788800 LAT 52.33149454614925000	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 53 LONG 5.07141744582948500 LAT 52.33137456092815000	
2022 Update Muiden	S1-S1.HN - M - 54 LONG 5.06820974739534250 LAT 52.32876234268489000	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 55 LONG 5.06771513970622100 LAT 52.32753200755565400	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 56 LONG 5.06720030433156400 LAT 52.32708670631106000	
2022 Update Muiden	S1-S1.HN - M - 57 LONG 5.06720319958923500 LAT 52.32696071963230000	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 58 LONG 5.06928773012011700 LAT 52.32634665381144000	
2022 Update Muiden	S1-S1.HN - M - 59 LONG 5.06876448210254200 LAT 52.32588746885176000	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 60 LONG 5.06747810483879000 LAT 52.33046570360906000	
2022 Update Muiden	S1-S1.HN - M - 61 LONG 5.06653503700967200 LAT 52.33058231311867600	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 62 LONG 5.06578030707485100 LAT 52.32831209620599000	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 63 LONG 5.06400866246321600 LAT 52.32794556670035000	
2022 Update Muiden	S1-S1.HN - M - 64 LONG 5.06365790904986000 LAT 52.32802692714312000	


Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 65 LONG 5.06333801312903700 LAT 52.32771514567130600	 
2022 Update Muiden	S1-S1.HN - M - 66 LONG 5.06205473043400600 LAT 52.32801597294177000	

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 67 LONG 5.06355132573267850 LAT 52.32789416472750000	
2022 Update Muiden	S1-S1.HN - M - 68 LONG 5.06171345464827300 LAT 52.32576428851973000	 

Project/State	sign	Details
2022 Update Muiden	S1-S1.HN - M - 69 LONG 5.05163364187623300 LAT 52.32874917161584000	

Project/State	sign	Details
2022 Update Naarden	S1-S1.HN - N - 47 LONG 5.15933873804181300 LAT 52.29605563493465000	
2022 Update Naarden	S1-S1.HN - N - 48 LONG 5.16246145146358600 LAT 52.29659278328475000	

Project/State	sign	Details
2022 Update Naarden	S1-S1.HN - N - 49 LONG 5.15995898273523500 LAT 52.29561483220614000	
2022 Update Naarden	S1-S1.HN - N - 50 LONG 5.16327017665000900 LAT 52.29570759516114000	

Project/State	sign	Details
2022 Update Naarden	S1-S1.HN - N - 51 LONG 5.16386108206708200 LAT 52.29541377493393400	
2022 Update Naarden	S1-S1.HN - N - 53 LONG 5.16445527285751900 LAT 52.29505704246478400	 

Project/State	sign	Details
2022 Update Naarden	S1-S1.HN - N - 54 LONG 5.16533447341848700 LAT 52.29519431307423000	

Project/State	sign	Details
2022 Update Naarden	S1-S1.HN - N - 55 LONG 5.15952037294255700 LAT 52.29405609441044000	

Project/State	sign	Details
2022 Update Naarden	S1-S1.HN - N - 56 LONG 5.16409369671408850 LAT 52.29368378112570000	
2022 Update Naarden	S1-S1.HN - N - 57 LONG 5.16074384974405200 LAT 52.29349492480965000	

Project/State	sign	Details
2022 Update Naarden	S1-S1.HN - N - 58 LONG 5.16293356061329400 LAT 52.29386259460771000	
2022 Update Bussum	S1-S1.HN - B - 76 LONG 5.16253104024482900 LAT 52.28001380833265400	

Project/State	sign	Details
2022 Update Bussum	S1-S1.HN - B - 77 LONG 5.24876616468637300 LAT 52.24019260590536400	
2022 Update Bussum	S1-S1.HN - B - 78 LONG 5.16606870184556900 LAT 52.27393691283259600	
2022 Update Bussum	S1-S1.HN - B - 79 LONG 5.16612140561712400 LAT 52.27366633668818000	

Project/State	sign	Details
2022 Update Bussum	S1-S1.HN - B - 80 LONG 5.16652195330828400 LAT 52.27393266916891000	
2022 Update Bussum	S1-S1.HN - B - 81 LONG 5.16667536586413000 LAT 52.27369086142503000	
2022 Update Bussum	S1-S1.HN - B - 82 LONG 5.16022458317476900 LAT 52.27331600309651000	

Project/State	sign	Details
2022 Update Bussum	S1-S1.HN - B - 83 LONG 5.15873571165046400 LAT 52.27770976321260000	
2022 Update Bussum	S1-S1.HN - B - 84 LONG 5.15781890646690300 LAT 52.28044355134535000	
2022 Update Bussum	S1-S1.HN - B - 85 LONG 5.15805620169209200 LAT 52.28084940989870000	

Project/State	sign	Details
2022 Update Bussum	S1-S1.HN - B - 86 LONG 5.17437367118758650 LAT 52.27560815697744000	
2022 Update Bussum	S1-S1.HN - B - 87 LONG 5.18135114005323900 LAT 52.26921304770845000	
2022 Update Bussum	S1-S1.HN - B - 88 LONG 5.17665555711685200 LAT 52.26829873989599000	

Project/State	sign	Details
2022 Update Bussum	S1-S1.HN - B - 89 LONG 5.16865127597380400 LAT 52.26727453207299600	
2022 Update Bussum	S1-S1.HN - B - 90 LONG 5.16844437952368500 LAT 52.26705279515768000	
2022 Update Bussum	S1-S1.HN - B - 91 LONG 5.16387748059368300 LAT 52.26660535598260500	

Project/State	sign	Details
2022 Update Bussum	S1-S1.HN - B - 92 LONG 5.16347483057201200 LAT 52.26673504896186000	
2022 Update Bussum	S1-S1.HN - B - 93 LONG 5.16377152006166450 LAT 52.26632003009284000	
2022 Update Bussum	S1-S1.HN - B - 94 LONG 5.16205086987039600 LAT 52.26348815112154000	

Project/State	sign	Details
2022 Update Bussum	S1-S1.HN - B - 95 LONG 5.17615303322140700 LAT 52.27349132599927000	
2022 Update Bussum	S1-S1.HN - B - 96 LONG 5.17249057991845350 LAT 52.27223099771101000	
2022 Update Bussum	S1-S1.HN - B - 97 LONG 5.17526729595428300 LAT 52.26961129286669000	

Project/State	sign	Details
2022 Update Bussum	S1-S1.HN - B - 101 LONG 5.15455832263441300 LAT 52.27690806133277000	
2022 Update Bussum	S1-S1.HN - B - 102 LONG 5.16279108958023800 LAT 52.27327713189336600	