




Previder Internet 300 Mb



Previder STAAS

CATTELAAR

Serverruimte

IS-0274 / Cisco 3750x / 100.127.0.61

IS-0256 / HP 2920 / 172.20.1.100

IS-0260 / HP 1910 / 172.20.1.29

IS-0195 / HP 1910 / 172.20.1.18

IS-0243 / HP 1910 / 172.20.1.26

IS-0244 / HP 1910 / 172.20.1.27

IS-0175 / 3com 5500g-el / 172.20.1.1

IS-0135 / 3com 5500g-el / 172.20.1.1

R-P01-0001 (LWOO)

IS-0234 / HP 1910 / 172.20.1.20

IS-0235 / HP 1910 / 172.20.1.21

IS-0236 / HP 1910 / 172.20.1.22

IS-0237 / HP 1910 / 172.20.1.23

IS-0183 / HP 1910 / 172.20.1.17

IS-0262 / HP 1910 / 172.20.1.31

IS-0289 / HP 1920 / 172.20.1.35

R-P02-0001

IS-0233 / HP 1910 / 172.20.1.19

IS-0155 / 3COM 4210 / 172.20.1.7

IS-0156 / 3COM 4210 / 172.20.1.8

IS-0242 / HP 1910 / 172.20.1.25

IS-0158 / 3COM 4210 / 172.20.1.10

IS-0247 / HP 1910 / 172.20.1.24

IS-0261 / HP 1910 / 172.20.1.30

IS-0291 / 3COM 4210 / 172.20.1.37

R-P04-0001

IS-0294 / HP 1920 / 172.20.1.38

IS-0307 / HP 1920 / 172.20.1.39

IS-0259 / HP 1910 / 172.20.1.28

R-P05-0001 (Noodlokaal)

IS-0287 / HP 1920 / 172.20.1.34

IS-0286 / HP 1920 / 172.20.1.33

Het Noordik

Noordikslaan

IS-0273 / Cisco 3750x / 100.127.0.68

Vriezenveen

IS-0275 / Cisco 3750x / 100.127.0.66

C. van Renneslaan

IS-0276 / Cisco 3750x / 100.127.0.67

Vroomshoop

IS-0279 / Cisco 3750x / 100.127.0.65

BOUWGILDE

B-P01-0001

IS-0280 / Cisco 3750x / 100.127.0.62

IS-0250 / HP 1910 / 172.20.4.1

IS-0251 / HP 1910 / 172.20.4.2

NOETSELERBERGWEG

Serverruimte

IS-0277 / Cisco 3750x / 100.127.0.63

IS-0239 / 3COM 4210 / 172.20.3.2

IS-0163 / 3COM 4210 / 172.20.3.11

IS-0149 / 5500G-EI / 172.20.3.1

IS-0258 / HP 2920 / 172.20.3.100

IS-0255 / HP 1910 / 172.20.3.20

IS-0192 / HP 1910 / 172.20.3.12

CA

IS-0245 / HP 1910 / 172.20.3.16

IS-0246 / HP 1910 / 172.20.3.17

IS-0254 / HP 1910 / 172.20.3.19

Lesplein technasium

IS-0176 / 3COM 4210 / 172.20.3.5

IS-0177 / 3COM 4210 / 172.20.3.6

IS-0253 / HP 1910 / 172.20.3.19

Noodlokaal

IS-0271 / HP 1910 / 172.20.3.21

Mediatheek

IS-0168 / 3COM 4210 / 172.20.3.4

IS-0164 / 3COM 4210 / 172.20.3.3

IS-0227 / HP 1910 / 172.20.3.14

Lokaal 301

IS-0169 / 3COM 4210 / 172.20.3.8

IS-0161 / 3COM 4210 / 172.20.3.7

WILLEM DE CLERQ

Serverruimte

IS-0278 / Cisco 3750x / 100.127.0.64

IS-0213 / HP 1910 / 172.20.2.10

IS-0148 / 5500G-EI / 172.20.2.1

IS-0225 / HP 1910 / 172.20.2.11

IS-0112 / 4500 / 172.20.2.2

IS-0257 / HP 2920 / 172.20.2.100

IS-0113 / 4500 / 172.20.2.2

IS-0114 / 4500 / 172.20.2.2

Synology DS409+

192.168.200.20

Ricoh RC gate

192.168.1.10

Boekenmagazijn

IS-0159 / 3COM 4210 / 172.20.2.8

IS-0160 / 3COM 4210 / 172.20.2.7

IS-0165 / 3COM 4210 / 172.20.2.9

IS-0226 / HP 1910 / 172.20.2.12

IS-0252 / HP 1910 / 172.20.2.13

Lokaal 32 H&A

IS-0167 / 3COM 4210 / 172.20.2.6

IS-0166 / 3COM 4210 / 172.20.2.5

10 Gb dar fiber

10 Gb dar fiber

10 Gb dar fiber

10 Gb dar fiber

10 Gb dar fiber

10 Gb dar fiber