

## FIELD SERVICE REPORT

6-03-2019

|                   |                   |                      |           |               |
|-------------------|-------------------|----------------------|-----------|---------------|
| Item Description  | Kast N°           | Contract Nr          |           |               |
| ZB-S              | 208-110-036 NV2+2 |                      |           |               |
| Unit Install date | 19-05-2001        | Battery Install date | 6-03-2019 |               |
| Battery Brand     | UPS               | Battery Type         | 12-150MRX | Nr.of Bats 18 |

|                       |                           |                   |                         |         |
|-----------------------|---------------------------|-------------------|-------------------------|---------|
| Customer:             |                           | Site Information: | Client ref:             |         |
| HAN Facilitaire zaken |                           | Site:             | HAN                     |         |
| Street:               | Postbus 5171              | Street:           | Ruitenberglaan 29       |         |
| PC:                   | NL 6802 ED City: Arnhem   | PC:               | NL 5836 CC City: Arnhem |         |
| Customer contact:     | Laurens Holtrigter        | Site contact:     |                         |         |
| Customer email:       | laurens.holtrigter@han.nl | Tel:              |                         | Mobile: |
| Customer PO:          |                           |                   |                         |         |

Reason for call / intervention:

Vervangen batterijset

Problems Found / solved

Batterijsetvervangen

Follow ups / Remarks:

Done : ☒ Maintenance ☐ Commissioned ☐ Checkup Installation ☐ New unit installed ☐ Installation Works

Replaced : ☐ Set of Batteries ☐ Defective Parts

To be done : ☐ Parts to be replaced ☐ Batterie(s) to be replaced ☐ Make a quotation

| Part Number | Description   | QTY | Labor Expenses     |       | code |
|-------------|---------------|-----|--------------------|-------|------|
|             | UPS 12-150MRX | 18  | Service work 1 (h) | 2:30  | 2:30 |
|             |               |     | Service work 2 (h) |       |      |
|             |               |     | Service work 3 (h) |       |      |
|             |               |     | Waiting time (h)   |       | 13   |
|             |               |     | Off Hours work (h) |       |      |
|             |               |     | Travel time (h)    | 2:00  | 2:00 |
|             |               |     | Kilometers (km)    | 148   | 148  |
|             |               |     | Start Time:        | 8:30  |      |
|             |               |     | Stop Time:         | 11:00 |      |

|           |                    |           |
|-----------|--------------------|-----------|
| Date      | Service Engineer 1 | Signature |
| 6-03-2019 | Bert Eilerts       |           |
|           | Service Engineer 2 |           |
|           |                    | Name:     |

System status

- ☒ NORMAL  
☐ Warning  
☐ Alarm  
☐ System OOO