

NDSM-helling Y2,3												
INDICATIEVE TELLING BETONSCHADES												
Helling Y2,3 met vide												
390												
tekeningnummer				m2		m2 geschat		m2				
		A	B	B	B	C	D	D	E	F	G	
B101	gevels	51	51					19		1		
gevels subtotaal	#VERW!	51	51	0	0	0	0	19	0	1	0	0
B111	kolom/wand deel 1	15	3			4	1			1		3
B112	kolom/wand deel 2	93	24			2	2			2		6
B113	kolom/wand deel 3	24	5							1		21
B114	kolom/wand deel 4	67	6				1			2		8
kolom/wand subtot	#VERW!	199	38	0	0	6	4	0	0	6	0	38
B121	onder dek deel 1	106	26				2			14	2	4
B122	onder dek deel 2	223	51				9			17		4
B123	onder dek deel 3	235	62			1	3			7	2	55
B124	onder dek deel 4	402	82	0,0		5	7			2	2	1
onderdek subtotaal	#VERW!	966	221	0,0	0	6	21	0	0	40	6	64
B131	op dek deel 1	16		128,2	32,8		1					54
B132	op dek deel 2	31		85,9	31,6		3					41
B133	op dek deel 3	25		122,8	22,6							21
B134	op dek deel 4	31		139,0	15,0		5					44
op dek subtotaal	#VERW!	103	0	475,9	102,0	0	9	0	0	0	0	160
totaal schades		1319	310	475,9	102,0	12,0	53,0	0,0	0,0	47,0	6,0	262,0
van bovengenoemde tekeningen												

